



# Swix Racing Service

## Wax Recommendation

---

### Event

Ranch Race, Jug Mountain, Donnelly, ID - Idaho Nordic Series Race #3

### Forecast

Friday: Lo 21F, 80% Chance of Snow - 1-3"  
Saturday: Hi 32F, 50% Chance of Snow - 1"  
Predicted at Race Time: 23F rising to 28F

### Structure

Apply T403 Broken V -OR- T401 Linear .75mm  
Even better: Geared Structure Tools: .3mm V \*\*If falling snow is wet put .3mm on tips, .5mm on tails.  
\*Apply after glide waxing is complete. Structure is always best applied the morning of the race.

### Glide Wax

Premium: HF7BW. Iron, scrape & brush first with Medium Bronze(T162) followed by Blue Nylon (T160)  
Economy: LF7. Iron, scrape & brush

Top Layer: FC1. Rotocorked, brush w/ Stiff Nylon or Horsehair followed w/ the Blue Nylon brush (T160). -OR- Apply FC7 Cera-F iron, brush w/ Stiff Nylon (T194), followed by the Wild Boar (T164). Finish w/ the Blue Nylon brush (T160).  
**Easy Option:FC8L (Universal Cera-F liquid)**, spread w/ felt pad, let dry 5 minutes, cork in, brush out w/ blue nylon.

### Kick Wax